

" Replacement DO need "

Sanwar Parvez

From: Sanwar Parvez <sanwar@cross-world.com>
Sent: Wednesday, June 30, 2021 11:54 AM
To: shipan@cross-world.com
Cc: habib@cross-world.com; zia@cross-world.com; harunor@cross-world.com; mefta@cross-world.com; moshiur@cross-world.com; sultan@cross-world.com; fahim@cross-world.com; adib@cross-world.com; sayeful@cross-world.com
Subject: Need Replacement DO for Meghna Ceramics

Dear Shipan,

Please make replacement DO as below:

CW will delivery:

3116938 KXA 51504-B-P11-5000 A-BOLT-ON-PANEL CONNECTION-4W

Mylar Type=F

1.0 PCS X 800 \$

3116860 KXA 51504-B-X-5000 A-BOLT-ON-SPECIAL LENGTH-4W

Mylar Type=F Class, X=500, Quantity=1

0.5 M X 693 \$

Return item from Meghna Ceramics:

KXA 51504-B-P11-5000 A-BOLT-ON-PANEL CONNECTION-4W (

Installed by local maintenance)

Mylar Type=F

X 800 \$

Reason for replacement by SP-

Damaged but by our inst. team, that is why we need to replace. SM

Note: Code: 3011703


(KXA 50504-B-X 5000 A-BOLT-ON-SPECIAL LENGTH-4W= 0.5 M X 693 \$
Mylar Type=F Class, X=500, Quantity=1) Already returned and it is now at our

warehouse.

Best Regards

Our DIC team consider the old version of the OC that is why we need to change. SM

Md. Sanwar Parvez | CROSS WORLD POWER LIMITED | Manager, Sales | Plot 1/B, Road 90, Gulshan 2, Dhaka 1212, Bangladesh | p: +880 2 5881 1858, 2222 91442 | f: +880 2 5881 5160 | m: 01777719792 | w: www.cross-world.com

 please consider the environment before printing this email

This communication contains information which is confidential and may also be privileged. It is for the exclusive use of the intended recipient(s).

From: Md. Ziaul Islam [mailto:zia@cross-world.com]

Sent: Wednesday, January 27, 2021 10:15 AM

To: Kartick Chandra Das; A.K.M. Ziaul Islam

Cc: Moshiur Rahman; Meftahul Zenan; Md. Fahim Muntasir; Hafizul Haque; Md. Sanwar Parvez; Sultan Sakauat Sarkar; Harunor Rashid; Maruf Ahmed

Subject: RE: Fwd:

Dear Sir,

Good Day from Cross World.

SM
6.7.21

Note:- please try to reduce the non standard item in the OC for and too much careful during the installation period.

SM
7.7.2021