CROSS WORLD POWER LTD



Warranty Claim

Sales Ref : CWPL-BE	T/0299/20					D	ate: Oct 05, 2021	
Bellow cutomer information to be filled in by Technical Division :					T	1.11	Zirabo Bazar, Ashulia EPZ	
Cutomer Name:	Ajax Sweater Limited		Tel/Fax:	01813302747	Address:	Road, Savar, Dhak	ta.	
			Perkins IIK	Engine Model:	1103A-33TG1	Engine S/N:	NA	
Genset Model :		Engine Brand:		Alternator Model:	P144J	Alternator S/N:	NA	
Plant Id:	NA	Alternator Brand:		/ Internator rest			1-101 20	
Warranty Information		First Stratdate :		Total Runtime :	1	Purchase Date:	Jul 01, 20	
Application Of Genset:	Main-supply	First Stratdate.		Total Table				
Failure and Replaceme	nt Information							
Failure/Complaint:	700							
Working environment (running conditions) and letails information		f flashing the feeder	box (63A-BB),	Burnt issues				
Working environment frunning conditions) at details information about the mulfunction (please kindly provide the details as much as possible):	actual reasons o	f flashing the feeder	box (63A-BB),	Burnt issues	net with as	Unit	Quar	ntity
Working environment running conditions) at details information about the mulfunction (please kindly provide the details as much as	actual reasons o	Product Name			net with as	Unit Pcs.	Quar 1	ntity
Working environment frunning conditions) and details information about the mulfunction (please kindly provide the details as much as possible): Failure part(if replaces	actual reasons o		3 A-FEEDER	BOX-5W	act with as		Quar	ntity
Working environment frunning conditions) and details information about the mulfunction (please kindly provide the details as much as possible): Failure part(if replaces	actual reasons o	Product Name KAP 0605-BB-6	3 A-FEEDER Grand Tot	BOX-5W			Quar 1 1	ntity
Working environment running conditions) at details information about the mulfunction please kindly provide the details as much as possible): Failure part(if replacer SL 1 Fault Causes	actual reasons o	Product Name KAP 0605-BB-6	3 A-FEEDER Grand Tot	BOX-5W		Pcs.	1	ntity
Working environment running conditions) at details information about the mulfunction (please kindly provide the details as much as possible): Failure part(if replacer SL 1 Fault Causes Preanalyze/Reson:	actual reasons o	Product Name KAP 0605-BB-6	3 A-FEEDER Grand Tot	BOX-5W al was loose(incoming sit	2 2	Pcs.	ainisa.	ntity
Working environment running conditions) at details information about the mulfunction (please kindly provide the details as much as possible): Failure part(if replaces SL 1 Fault Causes Preanalyze/Reson: Corrective Action:	actual reasons of ment is needed): Part S/N 4374 Initially found for Replaced with the second seco	Product Name KAP 0605-BB-6 feeder box internal conew one	3 A-FEEDER Grand Tot	BOX-5W al was loose(incoming sit	2 2	Pcs.	ainisa.	ntity
Working environment running conditions) at details information about the mulfunction (please kindly provide the details as much as possible): Failure part(if replacer SL 1 Fault Causes Preanalyze/Reson:	actual reasons o	Product Name KAP 0605-BB-6 feeder box internal conew one Delivery Date:	3 A-FEEDER Grand Tot	BOX-5W al was loose(incoming sit	2 2	Pcs.	ainisa.	ntity

tanager MSD HOD MSD HO

CWG-QM/FORM-0030D

Sloger

Revision No.:00 Page 1 of 1



