

najmul@cross-world.com

Work Order  
Re-work & Re-Installation

**From:** Engineer [engineering@qpail.com]  
**Sent:** Monday, June 17, 2019 3:59 PM  
**To:** Md. Fahim Muntasir  
**Cc:** Q Pail Limited; Md. Najmul Islam; Moshir Rahman; Sultan Sakauat Sarkar; Md. Ziaul Islam  
**Subject:** Re: Shifted one 400A power BBT from one side to another side.

Client: Xclusive Can Ltd (Phase-02)  
after ID: CWPL-BBT/0217/18F

Please, start work and finish the job. We will adjust the bill. waiting for reply.

Regards

Shohag

SP: Md. Najmul Islam.

**From:** Md. Fahim Muntasir <fahim@cross-world.com>

**Sent:** Sunday, June 16, 2019 12:08 PM

**To:** Engineer

Q Pail Limited; Md. Najmul Islam; Moshir Rahman; Sultan Sakauat Sarkar; Md. Ziaul Islam

**Subject:** RE: Shifted one 400A power BBT from one side to another side.

Dear Sir,  
Hope everything is going well.

As per trail email, Installed BBT dismantle & re-installation charge will need 10,000.00 TK. We shall wait for your reply.


Please note that, According to your conformation email will start this re-installation task.

Sl.	Description	Amount (TK)	Remarks
1	Riser BBT (Re-Works)	15,000.00	Task done.
2	400A BBT Re- installation.	10,000.00	
Total Amount (TK)		25,000.00	

You have required any further information, please feel free contact with us.

Best Regards,

**Md. Fahim Muntasir | Cross World Power Ltd.** | Asst. Engineer, Engineering Department | Plot 1/B, Road 90, Gulshan - 2, Dhaka 1212, Bangladesh | p: +880 2 5881 1858, 989 1442 Cell no: 01755694119 | f: +880 2 5881 5160 |  
M: fahim@cross-world.com | w: www.cross-world.com

 please consider the environment before printing this email

**From:** Engineer [mailto:engineering@qpail.com]

**Sent:** Friday, June 14, 2019 8:28 PM

**To:** Md. Fahim Muntasir; Md. Najmul Islam; moshir@cross-world.com

**Cc:** Q Pail Limited

**Subject:** Shifted one 400A power BBT from one side to another side.

Dear Najmul vai,

Hope you are doing well. you know that your technical team is working in our factory at 2nd floor. any how! may be from drawing mistake or the gap of cooperation, one line of 400A BBT has been installed in wrong side. I am cordially requesting you to ask your technician to install this line BBT as per our requirement. Please my dear brother/sir take action and solve the problem. waiting for your kind reply.

Regards