





## WARRANTY CLAIM FORM

BBT

Project Name:	Hop Yick Bangladesh Ltd		Date:	14/3/2018
Address:	Hop Yick Bangladesh Ltd. Unit-3, SFB#3 DEPZ, Savar			
Date Of Installation:	10/10/2017		Date Of Damages:	24/1/2018
Description of Damages:	KAP 0404-B-STD-40 A-STANDART LENGHT-6 WINDOW-4W-PAINTED Neutral pole burnt			
Replaceable Goods:	CODE	DESCRIPTION	QUANTITY	UNIT
	3048647	40A STANDART LENGHT-6 WINDOW-4W	2	pc
Remarks:	- M/C Plug defect found			
Image/Sample Attached	YES <input type="checkbox"/> NO <input type="checkbox"/>			
Reported By:	Remon Das		Designation:	Engineer
		 Signature & Date		
Recommendation for replacement:	 HOD		 COO/ GM-Sales	
Approved By:				
Availability (To be filled by Store Department)				
Ready Stock :	YES <input type="checkbox"/> NO <input type="checkbox"/> PARTIAL <input type="checkbox"/>			
Available goods for replacement in Ready Stock :	CODE	DESCRIPTION	QUANTITY	UNIT
Goods to import for replacement :	CODE	DESCRIPTION	QUANTITY	UNIT
Status of Technical & Commercial matter:				
Financial Approval				
 Signature & Date 15/3/18				