

Remon Das

Replacement DO need

**From:** Remon Das <remon@cross-world.com>  
**Sent:** Wednesday, March 21, 2018 4:40 PM  
**To:** 'Habibur Rahman'; 'Saiful Bashar'  
**Cc:** 'zia@cross-world.com'; 'sultan@cross-world.com'; 'fahim@cross-world.com'; 'Shipan Barua'; 'adib@cross-world.com'; 'maruf@cross-world.com'; 'najmul@cross-world.com'; 'haroon'  
**Subject:** Replacement of Plugs HOPLUN  
**Attachments:** IMG\_20180321\_160120.jpg

Dear Sir,

Please see the attached Delivery order of Hop lun BD Ltd. According to this delivery, client complaining us that there are 27 nos plugs has some mechanical fault (like screw missing, internal cord and cupper strip missing).

We have already inspected the supplied plugs and ensured the plugs were faulty. The faulty plugs already in our grip.

**Faulty Items:**

1. KAP 16-FS A PLUG WITH FUSE HOLDER – L1- 9 NOS
2. KAP 16-FS A PLUG WITH FUSE HOLDER – L2- 9 NOS
3. KAP 16-FS A PLUG WITH FUSE HOLDER – L3- 9 NOS

Thus now please kindly take necessary action to replace the faulty plugs.

Thanks.

Sales Ref: CWPL-BBT/0024/18  
DO Ref: CWPL-DO/0214/18

Regards,

**Remon Das | CROSS WORLD POWER LIMITED** | Engineer, Engineering Dept. | Plot 1/B, Road 90, Gulshan 2, Dhaka 1212, Bangladesh | p: (880 2) 5881 1858, 989 1442 | m: 01708483870 | f: (880 2) 5881 5160 | w: [www.cross-world.com](http://www.cross-world.com)

 please consider the environment before printing this email

This communication contains information which is confidential and may also be privileged. It is for the exclusive use of the intended recipient(s).