





WARRANTY CLAIM FORM

BBT

Project Name:	Unitex Composite Mills Ltd		Date:	20/02/2018
Address:	Bashbaria, Sitakunda, Chittagong			
Date Of Installation:	4/8/2017	Date Of Damages:	5/2/2018	
Description of Damages:	ROTARY HANDLE MALFUCTION AND CIRCUIT BREAKER PHASE DISCONTINUITY			
Replaceable Goods:	CODE	DESCRIPTION	QUANTITY	UNIT
	3030192	KOP 1651-II-160A-PLUG IN TAP OFF BOX-3P-SUITABLE FOR MCCB 5W (A=100A WITH MCCB, MODEL=XT1N, Icu= 36KA) (TAP OFF UNIT)	1	pc
Remarks:				
Image/Sample Attached	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>			
Reported By:	Remon Das		Designation:	Engineer
		 Signature & Date		
Recommendation for replacement:	 20/02/2018 HOD		 22/02/18 COO/ GM-Sales	
Approved By:				
Availability (To be filled by Store Department)				
Ready Stock :	YES <input type="checkbox"/> NO <input type="checkbox"/> PARTIAL <input type="checkbox"/>			
Available goods for replacement in Ready Stock :	CODE	DESCRIPTION	QUANTITY	UNIT
Goods to import for replacement :	CODE	DESCRIPTION	QUANTITY	UNIT
Status of Technical & Commercial matter:				
Financial Approval  Signature & Date				

Note: Should be claim for warranty replacement from EAE & the faulty TOB would be repaired locally.