

Md. Al- Miraj

From: Md.Abusieed Sobuj <sobuj@cross-world.com>
Sent: Monday, November 12, 2018 3:08 PM
To: Md. Al Miraj
Cc: Md. Habibur Rahman Javed; Md.Yezzum Hossain Sujon; ziaul islam; Sultan Sakauat Sarkar; Naba Krishna Mazumder
Subject: FW: Midland Bank Foyla Bazar Branch rubber pad installation issue.

Dear Miraj Vi,

Please find the below mail for price issue of subjected site and release the requisition for farther process.

Best Regards

Md. Abusieed sobuj | **CROSS WORLD LTD** | Engineer, Managed Service Division | Plot 1/B, Road 90, Gulshan 2, Dhaka 1212, Bangladesh | p: +880 2 5881 6528, 989 1442 | f: +880 2 5881 5160 | Mobile No: **+088 01755514856** | e: sobuj@cross-world.com | w: www.cross-world.com

From: Rahat Fahim Manwar [<mailto:manwar@cross-world.com>]
Sent: Monday, November 12, 2018 2:56 PM
To: Naba Krishna Mazumder
Cc: Md.Abusieed Sobuj; Sultan Sakauat Sarkar; ziaul islam
Subject: FW: Midland Bank Foyla Bazar Branch rubber pad installation issue.

Naba Vai,

FYKI...

Rahat Fahim Manwar | **CROSS WORLD POWER LTD** | Sr. Engineer , Engineering Dept. | House # 1/B, Road # 90, Gulshan - 2, Dhaka 1212, Bangladesh | p: +880 2 5881 1858, 989 1442 | f: +880 2 5881 5160 | m: 01755514874 | e: manwar@cross-world.com | w: www.cross-world.com

 please consider the environment before printing this email.

This communication contains information which is confidential and may also be privileged. It is for the exclusive use of the intended recipient(s).

From: ziaul islam [<mailto:zia@cross-world.com>]
Sent: Monday, November 12, 2018 2:54 PM
To: Rahat Fahim Manwar
Subject: Fw: Midland Bank Foyla Bazar Branch rubber pad installation issue.

Dear Manwar,

Please get the below price.

Best Regards,

Md. Ziaul Islam | CROSS WORLD POWER LTD | Head of Product, Pricing, Technical and Service | m: +88 01755514777 | e: zia@cross-world.com

From: aziz@cross-world.com

Sent: 12 November 2018 2:53 pm

To: maruf@cross-world.com

Cc: zia@cross-world.com; sayeful@cross-world.com

Subject: FW: Midland Bank Foyla Bazar Branch rubber pad installation issue.

Dear Sir

Please find bellow price

- 1) Rubber Pad (LXWXD-36''X 6''X 1'') -----02 pcs **Tk- 2500 (Unit Price)**
- 2) DG (20KVA) Lifting charge -----01 job (Lift up the DG to insert the rubber pads) - **Tk 3700 (Unit Cost)**

Regards

Md. Azizur Rahman | CROSS WORLD GROUP | Sr. Manager, Sourcing & Compliance | Plot 1/B, Road 90, Gulshan 2, Dhaka 1212, Bangladesh | p: +8802 8816528, 9891442 Cell no: 01755514788 | f: [+8802 8816205](tel:+88028816205) | e: aziz@cross-world.com | w: www.cross-world.com

 please consider the environment before printing this email.

From: Rahat Fahim Manwar [\[mailto:manwar@cross-world.com\]](mailto:manwar@cross-world.com)

Sent: Sunday, November 11, 2018 4:37 PM

To: Md. Azizur Rahman

Cc: ziaul islam; Sultan Sakauat Sarkar; Md.Abusieed Sobuj; Mahmudur Rahman

Subject: FW: Midland Bank Foyla Bazar Branch rubber pad installation issue.

Dear Sir,

Please provide price of the items of below mail urgently.

Rahat Fahim Manwar | CROSS WORLD POWER LTD | Sr. Engineer , Engineering Dept. | House # 1/B, Road # 90, Gulshan - 2, Dhaka 1212, Bangladesh | p: [+880 2 5881 1858](tel:+880258811858), 989 1442 | f: [+880 2 5881 5160](tel:+880258815160) | m: 01755514874 | e: manwar@cross-world.com | w: www.cross-world.com

 please consider the environment before printing this email.

This communication contains information which is confidential and may also be privileged. It is for the exclusive use of the intended recipient(s).

From: Naba Krishna Mazumder [<mailto:naba@cross-world.com>]
Sent: Sunday, November 11, 2018 10:13 AM
To: [Md.Abusieed](#) Sobuj
Cc: Sultan Sakauat Sarkar; [Md.Moazzem](#) Hossain; Rahat Fahim Manwar; ziaul islam
Subject: FW: Midland Bank Foyla Bazar Branch rubber pad installation issue.

Dear Sobuj Bhai,

Referring the below mail please proceed the following materials.

- 1) Rubber Pad (LXWXD-36''X 6''X 1'') -----02 pcs
- 2) DG (20KVA) Lifting charge -----01 job (Lift up the DG to insert the rubber pads)

Your kind consideration will be highly appreciated.

Best Regards

Naba K Mazumder | **CROSS WORLD POWER LTD** | Engineer, commissioning | Plot 1/B, Road 90, Gulshan 2, Dhaka 1212, Bangladesh | p: [+880 2 5881 1858](tel:+880258811858), 989 1442 | f: [+880 2 5881 5160](tel:+880258815160) | m: 01755514765 | e: naba@cross-world.com | w: www.cross-world.com

 please consider the environment before printing this email.

From: [Md.Yezzum](#) Hossain Sujan [<mailto:yezzum@cross-world.com>]
Sent: Sunday, November 11, 2018 9:41 AM
To: Naba Krishna Mazumder
Cc: Sultan Sakauat Sarkar; [Md.Abusieed](#) Sobuj; Ariful Islam; [Md.Moazzem](#) Hossain; ziaul islam
Subject: RE: Midland Bank Foyla Bazar Branch rubber pad installation issue.

Dear Naba Bhai

Please execute.

Thanks & Best regards,

Md Yezzum Hosain | CROSS WORLD GROUP | Engineer , Project Division | Plot 1/B, Road 90, Gulshan - 2, Dhaka 1212, Bangladesh | phone: **+880 2 5881 1858**, 989 1442 | fax: +880 2 5881 5160 | cell: **+880 17555 14778** | email: yezsum@cross-world.com web: www.cross-world.com

 please consider the environment before printing this email.

From: Naba Krishna Mazumder [<mailto:naba@cross-world.com>]

Sent: Saturday, November 10, 2018 8:06 PM

To: Md.Yezzum Hossain Sujan

Cc: Sultan Sakauat Sarkar; Md.Abusieed Sobuj; Ariful Islam; Md.Moazzem Hossain; ziaul islam

Subject: Midland Bank Foyla Bazar Branch rubber pad installation issue.

Dear Yezzum Bhai,

As per meeting with Midlands Bank, regarding the Foyla Bazar Branch 20KVA DG. We've to install the rubber pad & client will pay for this job.

Now the following materials will be needed for this job :

1) Rubber pad (size: LXWXD- 36"X6"X1")-02 pcs.

2) DG Lifting charge -----01 Job.

Please confirm me the above mentioned work. So I can proceed it at earliest time.

BR

Naba K Mazumder | CROSS WORLD POWER LTD | Engineer, Installation & commissioning | Plot 1/B, Road 90, Gulshan 2, Dhaka 1212, Bangladesh | p: **+880 2 5881 1858**, 989 1442 | f: +880 2 5881 5160 | m: 01755514765 | e: naba@cross-world.com | w: www.cross-world.com

please consider the environment before printing this email.