

WARRANTY CLAIM FORM

BBT

Project Name:	Hop Yick Bangladesh Ltd	Date:	14/3/2018
Address:	Hop Yick Bangladesh Ltd. Unit-3, SFB/3 DEPZ, Savar		

Date Of Supply:	7/2/2018	Date Of Damages:	7/2/2018
-----------------	----------	------------------	----------


Description of Damages:	KAP 16FS A PLUG WITH FUSE HOLDER L1- CUPPER STRIP MISSING KAP 16 FS A PLUG WITH FUSE HOLDER L2- SCREW MISSING KAP 16 FS A PLUG WITH FUSE HOLDER L3- LOCK UNLOCK KNOB TROUBLE		
-------------------------	--	--	--



Replaceable Goods:	CODE	DESCRIPTION	QUANTITY	UNIT
	3024554	KAP 16 FS A PLUG WITH FUSE HOLDER L3	9 ✓	pc
	3024555	KAP 16 FS A PLUG WITH FUSE HOLDER L2	9	pc
	3024556	KAP 16FS A PLUG WITH FUSE HOLDER L1	9	pc

Remarks:			
----------	--	--	--

Image/Sample Attached	YES ☐ NO ☐
-----------------------	--

Reported By:	Remon Das	Designation:	Engineer
--------------	-----------	--------------	----------

	 Signature & Date
--	---

Recommendation for replacement:	 HOD	 COO/ GM-Sales
---------------------------------	--	--

Approved By:	
--------------	--



Availability (To be filled by Store Department)				
---	--	--	--	--

Ready Stock :	YES ☒	NO ☐	PARTIAL ☐	
---------------	---	-----------------------------	----------------------------------	--

Available goods for replacement in Ready Stock :	CODE	DESCRIPTION	QUANTITY	UNIT
	3024554		09	
	3024555		08	
	3024556		09	

Goods to import for replacement :	CODE	DESCRIPTION	QUANTITY	UNIT

Status of Technical & Commercial matter:			
--	--	--	--

 27.04.18	Financial Approval  Signature & Date
---	---