## Fahim Muntasir

From:

Sultan Sakauat Sarkar <sultan@cross-world.com>

Sent: To:

Monday, December 10, 2018 2:36 PM

Cc:

Sharaban Tohura; Md. Fahim Muntasir; Meftahul Zenan; Md. Najmul Islam; Harunor

Rashid; ziaul islam; Md. Habibur Rahman Jabed; Moshiur Rahman; Shipan Barua RE: Regarding PY Garments materials issue,

Subject:

Importance:

High

Maruf Ahmed

Dear Sir,

Customer : PY Garments SP : Ar. Nazmul.

There is some intersections of power BBT at different area in this project hence below items has missed during order by our team. Our installation team has tried to complete installation without using this material but it will not be up to the mark from engineering ground. So requesting you to instruct concern person to deliver the materials at earliest.

3011973

KXA 10504-B-D-1000 A-BOLT-ON-DOWNWARDS ELBOW-4W

ADT 1.00

We are really sorry about this issue, hence taking this positively as a lesson.

We shall wait for your earlier action.

BR

Sultan Sakauat Sarkar | CROSS WORLD POWER LTD | Manager , MSD | House # 1/B, Road 90, Gulshan-02,

Dhaka 1212, Bangladesh | p: +880 2 5881 1858, 989 1442 | f: +880 2 5881 5160 | m:

01755514792 | e: sultan@cross-world.com | w: www.cross-world.com

From: Md. Fahim Muntasir [mailto:fahim@cross-world.com]

Sent: Monday, December 3, 2018 4:16 PM

To: Sultan Sakauat Sarkar Cc: Sharaban Tohura

Subject: Regarding PY Garments materials issue,

Dear Sir,

Below material has required to complete the 1000A BBT (Mezzanine Floor) installation task of PY Garments Ltd,

Comilla EPZ.

Please take necessary action regarding this issue.

KXA 10504-B-D-1000 A-BOLT-ON-DOWNWARDS ELBOW-4W

Best Regards,

Md. Fahim Muntasir | Cross World Power Ltd. | Asst. Engineer, Engineering Department | Plot 1/B, Road 90,

Gulshan - 2, Dhaka 1212, Bangladesh | p: +880 2 5881 1858, 989 1442 Cell no: 01755694119| f: +880 2 5881 5160 |

M: fahim@cross-world.com | w: www.cross-world.com

please consider the environment before printing this email