

## Fahim Muntasir

**From:** Raisa Haque <raisa@cross-world.com>  
**Sent:** Thursday, November 21, 2019 3:39 PM  
**To:** Maruf Ahmed  
**Cc:** Md. Ziaul Islam; Maruf Ahmed; Moshur Rahman; Md. Habibur Rahman Javed; Md. Sanwar Parvez; Shipan Barua; Md. Fahim Muntasir  
**Subject:** RE: Regarding banded BBT replacement issues for Saiham Sweater project.

Dear Sir,

As per prior email, we have already informed EAE & they have given feedback as "We are investigating the subject with our department, we will let you know once the investigation done."

Under this scenario, client is pursuing for supply of the replacement items (18 Nos of Items) from our stock.

Please advise.

Best Regards,

**Raisa Haque** | **CROSS WORLD POWER LTD** | Executive, Supply Chain | Plot 1/B, Road 90, Gulshan 2, Dha.  
1442 | f: +880 2 5881 5160 | e: [raisa@cross-world.com](mailto:raisa@cross-world.com) | w: [www.cross-world.com](http://www.cross-world.com)

 please consider the environment before printing this email

**From:** Shipan Barua [<mailto:shipan@cross-world.com>]  
**Sent:** Tuesday, November 19, 2019 3:31 PM  
**To:** Md. Fahim Muntasir  
**Cc:** Md. Ziaul Islam; Maruf Ahmed; Moshur Rahman; Md. Habibur Rahman Javed; Md. Sanwar Parvez; Raisa Haque  
**Subject:** RE: Regarding banded BBT replacement issues for Saiham Sweater project.

Dear Fahim vai,  
Below materials are available in our ready stock till today (19.11.2019)  
Which is shown in table

*Maruf*  
11/12/19

*Requested EAE (At Meeting) -*

*Raisa Haque*  
11/12/19

*Warranty Replacement of Raiser Sweater is available*  
*Confirmation of Raiser Sweater*  
*18 Nos of Raiser Sweater*  
*01/12/19*  
*Off*  
*\* Arrange for delivery*  
*\* Appraisal*

**Subject:** FW: Regarding banded BBT replacement issues for Saiham Sweater project.

**From:** Shipan Barua [mailto:shipan@cross-world.com]

**Sent:** Tuesday, November 19, 2019 3:31 PM

**To:** Md. Fahim Muntasir

**Cc:** Md. Ziaul Islam; Maruf Ahmed; Moshir Rahman; Md. Habibur Rahman Jabed; Md. Sanwar Parvez; Raisa Haque

**Subject:** RE: Regarding banded BBT replacement issues for Saiham Sweater project.

Dear Fahim vai,

Below materials are available in our ready stock till today (19.11.2019)

Which is shown in table

| SL | BBT Rating | BBT Model                                             | QTY       | Length                | Picture Number                                      | Reff. Date | Code    | BBT Materials                                     | Remarks            |
|----|------------|-------------------------------------------------------|-----------|-----------------------|-----------------------------------------------------|------------|---------|---------------------------------------------------|--------------------|
| 1  | 40A BBT    | KAP 0404 – STD - 40A<br>Standard Length – 4<br>Window | 01<br>pcs | Standard-<br>(3Meter) | 11.11.19 _<br>Pic - 01<br>to 11.11.19<br>_ Pic - 06 | 11.11.2019 | 3048649 | KAP 0405-STD-40 A-STANDART LENGHT-<br>6 WINDOW-5W | Available In Stock |
| 2  | 25A BBT    | KAM 0204 – STD - 25A<br>Standard Length – 4<br>Window | 01<br>pcs | Standard-<br>(3Meter) |                                                     |            |         |                                                   | Nil                |
| 3  | 40A BBT    | KAP 0404 – STD - 40A<br>Standard Length – 4<br>Window | 02<br>pcs | Standard-<br>(3Meter) | 16.11.19 _<br>Pic - 01<br>to 16.11.19<br>_ Pic - 05 | 16.11.2019 | 3048649 | KAP 0405-STD-40 A-STANDART LENGHT-<br>6 WINDOW-5W | Available In Stock |
| 4  | 63A BBT    | KAP 0604 – STD - 63A<br>Standard Length – 4<br>Window | 01<br>pcs | Standard-<br>(3Meter) | 18.11.19 _<br>Pic - 01<br>to 18.11.19<br>_ Pic - 37 | 18.11.2019 | 3025078 | KAP 0604-STD-63 A-STANDART LENGHT-<br>4 WINDOW-4W | Available In Stock |
| 5  | 100A BBT   | MKA 1054-STD-100 A-<br>STANDARD LENGTH-4W             | 06<br>pcs | Standard-<br>(3Meter) |                                                     |            | 3024402 | MKA 1054-STD-100 A-STANDARD<br>LENGTH-4W          | Available In Stock |

|   |          |                                                 |           |                   |  |  |         |                                               |                    |
|---|----------|-------------------------------------------------|-----------|-------------------|--|--|---------|-----------------------------------------------|--------------------|
| 6 | 160A BBT | MKA 1654-STD-160 A-STANDARD LENGTH-4W           | 04<br>pcs | Standard-(3Meter) |  |  | 3024741 | MKA 1654-STD-160 A-STANDARD LENGTH-4W         | Available In Stock |
| 7 | 40A BBT  | KAP 0404 – STD - 40A Standard Length – 4 Window | 03<br>pcs | Standard-(3Meter) |  |  | 3048649 | KAP 0405-STD-40 A-STANDART LENGHT-6 WINDOW-5W | Available In Stock |

Best Regards

**Shipan Barua** | **CROSS WORLD POWER LIMITED** | Engineer, Customer Relations | | Plot 1/B, Road 90, Gulshan 2, Dhaka 1212, Bangladesh | p: +880 2 5881 1858, 989 1442 | Cell : 01708483874 | f: +880 2 5881 5160 | w: [www.cross-world.com](http://www.cross-world.com)



please consider the environment before printing this email

---

**From:** Md. Fahim Muntasir [<mailto:fahim@cross-world.com>]  
**Sent:** Monday, November 18, 2019 1:35 PM  
**To:** Shipan Barua  
**Cc:** Sultan Sakauat Sarkar  
**Subject:** FW: Regarding banded BBT replacement issues for Saiham Sweater project.  
**Importance:** High

Dear Shipan Vi,  
As per trail mail, Please ensure to us, Which materials available at our ready stock or not (Instructed by Maruf sir).

Best Regards,

**Md. Fahim Muntasir** | **Cross World Power Ltd.** | Asst. Engineer, Engineering Department | Plot 1/B, Road 90, Gulshan - 2, Dhaka 1212, Bangladesh | p: +880 2 5881 1858, 989 1442  
Cell no: 01755694119 | f: +880 2 5881 5160 | M: [fahim@cross-world.com](mailto:fahim@cross-world.com) | w: [www.cross-world.com](http://www.cross-world.com)