

CROSS WORLD POWER LTD



Warranty Claim

WCF-0001/ASL/21

Sales Ref : CWPL-BBT/0299/20

Date : Oct 05, 2021

Below customer information to be filled in by Technical Division :

Customer Name :	Ajax Sweater Limited	Tel/Fax :	01813302747	Address :	Zirabo Bazar, Ashulia EPZ Road, Savar, Dhaka.
Genset Model :		Engine Brand :	Perkins, UK	Engine Model :	403A-33TC1
Plant Id :	NA	Alternator Brand :		Alternator Model :	01447
Engine S/N :		Alternator S/N :			NA

Warranty Information	Application Of Genset :	Main-supply	First Startdate :		Total Runtime :	1	Purchase Date :	Jul 01, 20
----------------------	-------------------------	-------------	-------------------	--	-----------------	---	-----------------	------------

Failure and Replacement Information

Failure/Complaint :

Working environment (running conditions) and details information about the malfunction (please kindly provide the details as much as possible):

actual reasons of flashing the feeder box (63A-B5), Burnt issues

Failure part(if replacement is needed):

SL	Part S/N	Product Name	Unit	Quantity
1	4374	KAP 0605-B5-63 A FEEDER BOX-5W	Pcs.	1
Grand Total				

Fault Causes Initially found feeder box internal connection bolt was loose(incoming site)

Presanlyze/Reason :

Corrective Action : Replaced with new one

Warranty Information

LC Date :	Jul 01, 20	Delivery Date :		Warranty Start Date :	18.12.2020	Warranty expiry date :	
-----------	------------	-----------------	--	-----------------------	------------	------------------------	--

Conclusion : Under Warranty(Approved)

Manager MSD

HOD MSD

CRM

Finance Clearance

This form must be submitted to Finance within seven(7) days of the repair date.

