

WARRANTY CLAIM FORM

BBT

Project Name:	Unitex Composite Mills Ltd	Date:	15/04/2018
Address:	Bashbaria, Sitakunda, Chittagong		

Date Of Installation:	4/8/2017 ✓	Date Of Damages:	13/04/2018
-----------------------	------------	------------------	------------

Description of Damages: Found panel connection unit phase to phase Insulation damaged, measured load current L1 2172A, L2 1998A, L3 2056A




	CODE	DESCRIPTION	QUANTITY	UNIT
Replaceable Goods:	3013929	KXA 33504-B-P11-3200A- BOLT ON PANEL CONNECTION-4W (DISTRIBUTION BOARD CONNECTION UNIT) ✓	1	pc
	3011691	KXA 33504-B-X-3200A- BOLT ON SPECIAL LENGTH-4W (X=600, QUANTITY 1) ✓	1	pc

Remarks:

Image/Sample Attached ☒ YES ☐ NO ☐

Reported By:	Remon Das	Designation:	Engineer
--------------	-----------	--------------	----------


 15/4/18
 Signature & Date

Recommendation for replacement:	 10/4/18	 16/04/2018	 21/05/2018
---------------------------------	--	--	---

Approved By:	✓ HOD	COO/ GM-Sales
--------------	-------	---------------

Availability (To be filled by Store Department)


Ready Stock : YES ☐ NO ☐ PARTIAL ☐


	CODE	DESCRIPTION	QUANTITY	UNIT
Available goods for replacement in Ready Stock :	3013929		01	Pcs

	CODE	DESCRIPTION	QUANTITY	UNIT
Goods to import for replacement :	3011691	Goods to import for replent.	01	Pcs

Status of Technical & Commercial matter:

Financial Approval


 Signature & Date


 21/5/18